

Fabian Salazar
Air Safety Investigator
Western Pacific Region

Date: February 27, 2024

Subject: Text Messages

Figure one is the text message communication between the accident PIC and the Director of Maintenance made during the reposition flight from Camarillo Airport (CMA) Camarillo, California to the Bob Hope Airport (BUR) Burbank, California.




Figure 1. Text message from the accident PIC to the Director of Maintenance. Source, Orbic Air.

Figures two and three are the text message communications between the accident PIC and the Flight Follower.




Figure 2. Page one of text message from the accident PIC to the Flight Follower. Source Orbic Air.




Figure 3. Page two of the text message sent from the accident PIC to the Flight Follower. Source Orbic Air.