

CEN25FA006

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage Overview (Courtesy of Norfolk Police Department)



Photograph 2 - Wreckage Overview Closeup (Courtesy of Textron Aviation)



Photograph 3 - Left Engine (Courtesy of Textron Aviation)



Photograph 4 - Left Propeller



Photograph 5 - Right Engine and Propeller