


CEN25LA013

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident helicopter in cornfield (Courtesy of Law Enforcement)**



**Photograph 2 - Broken tail rotor belt (Courtesy of Owner)**



**Photograph 3 - Frayed tail rotor belt (Courtesy of Owner)**