

CEN25LA020

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Ventral Stabilizer Damage (Courtesy of Addison Airport Manager)



Photograph 2 - Ventral Stabilizer Damage (Courtesy of Addison Airport Manager)