

National Transportation Safety Board

Office of Aviation Safety  
Central Region

CEN25LA025

## **INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Accident airplane (Courtesy of FAA)**



**Photograph 2 - Left lower wing damage (Courtesy of FAA)**



**Photograph 3 - Left lower wing aileron damage (Courtesy of FAA)**