

CEN25LA032

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of FAA)



Photograph 2 - Damaged left horizontal stabilizer (Courtesy of FAA)