

CEN25LA038

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Helicopter (Courtesy of Property Owner)



Photograph 2 - Accident Helicopter (Courtesy of Property Owner)



Photograph 3 - Engine Coolant Hose (NTSB Photo)



Photograph 4 - Engine Cylinder Wall (NTSB Photo)