

CEN25LA046

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the fuselage and the engine at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the empennage and the engine at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the cockpit at the accident site (courtesy of the Federal Aviation Administration)



**Photograph 4 - View of the aircraft recovered from the accident site and inside of a hangar
(courtesy of the Federal Aviation Administration)**