

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN25LA064

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane being recovered (Courtesy of FAA)



Photograph 2 - Ground scars (Courtesy of FAA)



Photograph 3 - Accident airplane being recovered (Courtesy of FAA)