

CEN25LA067

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the helicopter at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the bottom of the helicopter at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the rear of the helicopter at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the top of the helicopter at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the windsock at the accident site (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the helipad material, an artificial turf (courtesy of the Federal Aviation Administration)



Photograph 7 - View of the right side skid and the artificial turf (courtesy of the Federal Aviation Administration)