

CEN25LA070

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Nose (Operator Photo)




Photograph 2 - Airplane Nose (Operator Photo)




Photograph 3 - Right Side of Forward Fuselage (Operator Photo)



Photograph 4 - Left Side of Forward Fuselage (Operator Photo)



Photograph 5 - Right Side Windshield (Operator Photo)



Photograph 6 - Vertical Stabilizer (Operator Photo)