

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN25LA075

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident airplane entangled
In high-tension power line (Courtesy of FAA)**



**Photograph 2 - Accident airplane entangled
In high-tension powerline (Courtesy of FAA).**



Photograph 3 - Accident airplane after having been lowered to the ground in valley between power line poles (Courtesy of FAA)



Photograph 4 - Accident airplane after having been removed from the power line (Courtesy of FAA)