

CEN25LA078

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane, left side (Courtesy of FAA)



Photograph 2 - Accident airplane, right side (Courtesy of FAA)



Photograph 3 - Right wing damage (Courtesy of FAA)