

CEN25LA081

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Accident site (Courtesy of FAA)



Photograph 3 - Accident site (Courtesy of FAA)




Photograph 4 - Fuel Selector (Courtesy of NTSB)



Photograph 5 - Carburetor (Courtesy of NTSB)



Photograph 6 - Fuel strainer bowl contaminants (Courtesy of NTSB)



Photograph 7 - Mixture control cable and carburetor (Courtesy of NTSB)



Photograph 7 - Mixture control arm and hardware (Courtesy of NTSB)