

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN25LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Landing gear selector (Courtesy of FAA)



Photograph 3 - Damage to airplane (Courtesy of FAA)