

CEN25LA089

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident Airplane (Source: Pilot)**



**Photograph 2 - Accident airplane (Source: Airport Representative)**



**Photograph 3 - Left main landing gear after recovery (Source: Airport Representative)**