

CEN25LA093

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Helicopter (Courtesy of Pilot)



Photograph 2 - Accident Helicopter (Courtesy of Pilot)



Photograph 3 - Damaged Number 3 Cylinder Intake Valve (Courtesy of FAA)