

CEN25LA099

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantially Damaged Airplane (Courtesy of FAA)



Photograph 2 - Side View of Accident Airplane (Courtesy of FAA)