

CEN25LA105

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Separated Anchor Point (Courtesy of NTSB)



Photograph 2 - Separated Anchor Point (Courtesy of NTSB)