

CEN25LA110

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Fuselage damage (Courtesy of FAA)