

CEN25LA117

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane in a field (Courtesy of the Pilot/Owner)



Photograph 2 - Accident airplane in a field (Courtesy of the Pilot/Owner)



Photograph 3 - Broken engine mount (Courtesy of the Pilot/Owner)