

CEN25LA121

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of Accident Airplane (Courtesy of Federal Aviation Administration)



Photograph 2 - Right Wing Damage (Courtesy of Federal Aviation Administration)



Photograph 3 - Empennage Damage (Courtesy of Federal Aviation Administration)