

CEN25LA133

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane on runway (Courtesy of FAA)



Photograph 2 - Damaged longerons on belly of airplane (Courtesy of FAA)