

CEN25LA145

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (FAA Photo)



Photograph 2 - Accident Airplane (FAA Photo)



Photograph 3 - Nose Landing Gear (FAA Photo)



Photograph 4 - Engine (FAA Photo)



Photograph 5 - Engine Mount (FAA Photo)



Photograph 6 - Engine Mount (FAA Photo)



Photograph 7 - Engine Mount (FAA Photo)



Photograph 8 - Airplane Data Plate (FAA Photo)