

CEN25LA146

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site with the left wing separated (courtesy of the flight instructor)



Photograph 2 - View of the rear of the airplane at the accident site (courtesy of the flight instructor)



Photograph 3 - View of the front of the airplane at the accident site with the left wing recovered (courtesy of the flight instructor)