

CEN25LA149

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Accident site (FAA photo)



Photograph 2 - Accident site (FAA photo)



Photograph 3 -Accident site (FAA photo)



Photograph 4 - Airplane during examination (NTSB photo)




Photograph 5 - Airplane during examination (NTSB photo)



Photograph 6 - Aft fuselage / empennage (NTSB photo)



Photograph 7 - Engine / propeller (NTSB photo)



Photograph 8 - Engine / propeller (NTSB photo)