


CEN25LA163

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of the accident site at night (courtesy of the Hartford Fire Department)



Photograph 2 - View of the helicopter and the tree it impacted at night (courtesy of the Hartford Fire Department)



Photograph 3 - View of the helicopter and the tree it impacted at night (courtesy of the Hartford Fire Department)



Photograph 4 - View of the front of the helicopter at the accident site at night (courtesy of the Hartford Fire Department)



Photograph 5 - View of the left side of the helicopter at the accident site at night (courtesy of the Hartford Fire Department)



Photograph 6 - View of the rear of the helicopter at the accident site at night (courtesy of the Hartford Fire Department)



Photograph 7 - View of the right side of the helicopter at the accident site at night (courtesy of the Hartford Fire Department)



Photograph 8 - View of the postimpact fire initiating at night (courtesy of the Hartford Fire Department)



Photograph 9 - View of the accident site with the helicopter during the day, approximately facing to the north (courtesy of Air Methods)



Photograph 10 - View of the accident site with the helicopter during the day, approximately facing to the east (courtesy of Air Methods)



Photograph 11 - View of the accident site with the helicopter during the day, approximately facing to the south (courtesy of Air Methods)



Photograph 12 - View of the accident site with the helicopter during the day, approximately facing to the west (courtesy of Air Methods)