

CEN25LA164

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Right Pontoon and Oil Slick (Courtesy of the Canadian Coast Guard)



Photograph 2 - ADS-B Graphic Depiction (Courtesy of The Transportation Safety Board, Canada)



Photograph 3 - N4025K (Courtesy of Wipaire Inc.)




Photograph 4 - ADS-B Plots (Courtesy of The Transportation Safety Board, Canada)



Photograph 5 - Recovered Right Pontoon (Courtesy of the Canadian Coast Guard)



Photograph 6 - Recovered Liferaft (Courtesy of the Canadian Coast Guard)



Photograph 7 - Liferaft Information (Courtesy of the Canadian Coast Guard)