

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA172

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site, Front (Courtesy of FAA)



Photograph 2 - Airplane at Accident Site, Front/Right (Courtesy of FAA)



Photograph 3 - Airplane at Accident Site, Rear/Right (Courtesy of FAA)