

CEN25LA174

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Worn Left Tire with Flat Spot (Courtesy of Federal Aviation Administration)



Photograph 3 - Left Wing Damage (Courtesy of Federal Aviation Administration)