

CEN25LA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Abrasion damage (Courtesy of FAA)



Photograph 2 - Accident airplane (Courtesy of FAA)