

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA191

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site, Left (Courtesy of Pilot)



Photograph 2 - Airplane at Accident Site, Front/Right (Courtesy of Pilot)



Photograph 3 - Airplane at Accident Site, Right (Courtesy of Pilot)



Photograph 4 - Airplane at Accident Site, Rear (Courtesy of Pilot)