

CEN25LA195

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the airplane (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the nose landing gear, which sustained a flat tire (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the left side fuselage, just aft of the engine compartment (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the lower left side of the cockpit (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the lower left side of the cockpit (courtesy of the Federal Aviation Administration)