

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA210

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site, Right (Courtesy of Airport Operations)



Photograph 2 - Airplane at Accident Site, Front/Left (Courtesy of Airport Operations)




Photograph 3 - Airplane at Accident Site, Rear/Left (Courtesy of Airport Operations)



Photograph 4 - Left Main Landing Gear (Courtesy of FAA)



Photograph 5 - Fuselage Damage (Courtesy of FAA)



Photograph 6 - Left Wing Damage (Courtesy of FAA)