

CEN25LA213

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter at Accident Site (FAA Photo)



Photograph 2 - Helicopter at Accident Site (FAA Photo)



Photograph 3 - Horizontal Stabilizers (FAA Photo)



Photograph 4 - Fenestron and Tailboom (FAA Photo)