

CEN25LA227

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Lower Fuselage Substantial Damage (Courtesy of FAA)



Photograph 2 - Lower Fuselage Substantial Damage (Courtesy of FAA)