

CEN25LA231

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Airplane's right side (Courtesy of FAA)



Photograph 3 - Airplane's left side (Courtesy of FAA)



Photograph 4 - Engine and Propeller (Courtesy of FAA)