

CEN25LA246

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the airplane (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the rudder (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the tailwheel (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the underside of the empennage (courtesy of the Federal Aviation Administration)