

CEN25LA257

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the airplane after it was recovered from the water (courtesy of the airport manager)



Photograph 2 - Right side view of the airplane after it was recovered from the water (courtesy of the airport manager)



**Photograph 3 - View of the right wing after the airplane was recovered from the water
(courtesy of the airport manager)**



Photograph 4 - View of the right wing of the airplane inside of a hangar (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the right wing of the airplane inside of a hangar (courtesy of the Federal Aviation Administration)