

CEN25LA260

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of pilot)



Photograph 2 - Right wing damage (Courtesy of pilot)