

CEN25LA276

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Federal Aviation Administration)



Photograph 2 – Right Wing (Courtesy of Federal Aviation Administration)



Photograph 3 - Power Line (Courtesy of Federal Aviation Administration)