

CEN25LA279

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side of the Airplane



Photograph 2 - Right Wing Tip



Photograph 3 - Instrument Panel