

CEN25LA287

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane right side (Courtesy of 8D1 Airport Manager)**



**Photograph 2 - Tail (Courtesy of 8D1 Airport Manager)**



**Photograph 3 - Rear fuselage and tailspring (Courtesy of 8D1 Airport Manager)**



**Photograph 4 - Tailspring and tailwheel assembly (Courtesy of FAA)**