


CEN25LA312

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Network time is not synchronized
Local: Aug 9, 2025 at 11:13:26 CDT
N 35° 40' 48.846", W 93° 43' 27.082"
225° SW

Photograph 2 - View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the fuselage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the empennage at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the cockpit at the accident site (courtesy of the Federal Aviation Administration)