

CEN25LA315

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Right Horizontal Stabilizer Damage (Courtesy of Federal Aviation Administration)