

CEN25LA329


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site. (Courtesy of FAA)



Photograph 2 - Broken landing gear. (Courtesy of FAA)



Photograph 3 - Fuselage after recovery. (Courtesy of Insurance)