

CEN25LA331

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Lift Strut Damage (Courtesy of Federal Aviation Administration)