

CEN25LA345

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Accident Site (Courtesy of FAA)



Photograph 3 - Cockpit Damage (Courtesy of FAA)