

CEN25LA372

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Freeman Municipal Airport Manager)



Photograph 2 - Right Wing Damage (Courtesy of Freeman Municipal Airport Manager)



Photograph 3 - Right Fuselage Damage (Courtesy of Freeman Municipal Airport Manager)



Photograph 4 - Left Wing Damage (Courtesy of Freeman Municipal Airport Manager)