

CEN25LA376

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane after the accident. (Courtesy of FAA)



Photograph 2 - Right horizontal stabilizer and elevator after the accident (Courtesy of FAA)